

## Abstract

A method of relieving surface stress on a thin wafer by removing a small portion of the wafer substrate, the substrate being removed by applying a solution of KOH to the wafer while 5 the wafer spins.